



Department of
Environmental
Conservation

Spill Incidents Database Search Details

Spill Record

Administrative Information

DEC Region: 3

Spill Number: 1807241

Spill Date/Time

Spill Date: 10/07/2018 **Spill Time:** 07:13:00 AM

Call Received Date: 10/07/2018 **Call Received Time:** 07:24:00 AM

Location

Spill Name: SKYDIVE THE RANCH

Address: 57 SAND HILL ROAD

City: GARDINER **County:** Ulster

Spill Description

Material Spilled Amount Spilled Resource Affected

jet fuel 2000 Gal. Soil , Surface Water

Cause: Human Error

Source: Gasoline Station or other PBS Facility

Waterbody: WALLKILL

PBS #:

Record Close

Date Spill Closed: Not closed

If you have questions about this reported incident, please contact the Regional Office where the incident occurred.



**Department of
Environmental
Conservation**

Bulk Storage Database Search Details

Facility Information

Site No.: 3-601643

Status: Active

Expiration Date: 02/28/2019

Site Type: PBS

Facility Type: Other

Site Name: GARDINER - WILLIAM RICHARDS

Address: 45 SAND HILL ROAD

Locality: GARDINER

State: NY

Zipcode: 12525

County: Ulster

Facility(Property) Owner(s) Information

Facility Owner: WILLIAM RICHARDS

PO BOX 136 . GARDINER, NY. 12525

Mail Contact:

PO BOX 136 . GARDINER, NY. 12525

Facility Operator

Facility Operator: GARDINER - WILLIAM RICHARDS

Tank Information

1 Tanks Found

Tank No	Tank Location	Status	Capacity (Gal.)
1	Aboveground on saddles, legs, stilts, rack or cradle	In Service	9000

Refine This Search

Return To Results



Department of
Environmental
Conservation

Bulk Storage Database Search Details

Tank Information

Site No: 3-601643

Site Name: GARDINER - WILLIAM RICHARDS

Tank No: 1

Tank Location: Aboveground on saddles, legs, stilts, rack or cradle

Subpart: 4

Category: 2

Tank Status: In Service

Tank Install Date: 09/01/2000

Tank Closed Date:

Tank Out Of Service Date:

Tank Capacity: 9000 gal.

Product Stored: kerosene [#1 fuel oil] (on-site consumption)

Percentage: 100%

Tank Type: 01 - Steel/Carbon Steel/Iron

Tank Internal Protection: Epoxy Liner

Tank External Protection: Painted/Asphalt Coating

Tank Secondary Containment: Double-Walled (Underground)

Tank Leak Detection: None

Overfill: High Level Alarm

Overfill: Automatic Shut-Off

Spill Prevention: Catch Basin

Dispenser: Suction Dispenser

Pipe Location: Aboveground/Underground Combination

Pipe Type: Steel/Carbon Steel/Iron

Pipe External Protection: None

Piping Secondary Containment: None

Piping Leak Detection: Exempt Suction Piping

UDC: Yes

Tank Next Test Due:

Tank Last Test:

Tank Test Method:

Line Next Test Due:

Line Last Test:

Line Test Method: